



NOTICE TO AIRMEN

NO. 33/1937.

(CANCELS No. 5/1925)

JUNGA, W.A.



CLASS OF GROUND: Emergency Landing Ground.
PROPRIETORS: Civil Aviation Board, Melbourne.
POSITION: At angle in tel. line 11 miles S.E. of Murchison House Station. Lat.: 27° 44' S. Long.: 114° 22' E.
MAGNETIC VARIATION: 3° West approx.
LANDMARKS: Water tanks and shed South-West of ground.
MARKINGS: White cross and wind indicator.
SURFACE: Sandy (sand plain cleared and levelled).
DIMENSIONS: North-South 660 yards; East-West 700 yards.
HEIGHT ABOVE SEA LEVEL: 250 ft. approx.
APPROACHES: Clear, except tel. line 20 ft. high, about 200 yards East.
SURROUNDING COUNTRY: Sand plain. Forced landing might entail minor damage and difficult take-off, as surface is somewhat rough.
PETROL, OIL AND WORKSHOPS: Northampton, 46 miles South. (Try Murchison House, 11 miles North-West).
WATER SUPPLY: At rain shed South-West of ground.
HANGAR ACCOMMODATION: Nil.
TELEPHONE AND TELEGRAPH: Ajana P.O., 20 miles South-East.
NEAREST SETTLEMENT: Murchison House.
RAILWAY STATION: Ajana.
CHARGES: Nil.
REMARKS: A sand-plain ground, which should only be used in case of necessity. Access is difficult. Surface is liable to be very friable in summer. After heavy rains the northern and eastern portions should be used. Murchison House Station is the only settlement in the locality.
 Strip-map No. 53.

S. A. Crawford

Secretary,
Civil Aviation Board.